




Software for Additive manufacturing



+ Question #1 08/10/2015



An STL file describes




| | | |
|-----------------------|-----------|-------|
| a surface | 12 | 38.7% |
| a volume | 6 | 19.4% |
| a machine toolpath | 2 | 6.5% |
| a wireframe CAD model | 11 | 35.5% |
| Other | 0 | 0% |

+ Question #2 08/10/2015



The G-code is



| | | |
|---------------------------|----|-------|
| is sequentially processed | 13 | 43.3% |
| is processed in parallel | 6 | 20% |
| represents the 3D model | 10 | 33.3% |
| Other | 1 | 3.3% |

+ Additive manufacturing

Process Flow

- Solid Modelling
- Tessellation/Generation of STL file
- Support Generation
- “Slicing” of the Model
- Model Physical Buildup
- Cleanup and Post Curing
- Surface Finishing



+ Additive manufacturing Process Flow




File



Description




Software




EXCHANGE FORMATS



+ Example of *.stl Representation



+ Example of *.stl Representation



Representing
a sphere



```
solid obj1
facet normal 1.457591e-01 -9.885599e-01 -3.877669e-02
  outer loop
    vertex 9.614203e+00 4.757629e+00 0.000000e+00
    vertex 7.875000e+00 4.501190e+00 0.000000e+00
    vertex 9.483117e+00 4.764183e+00 -6.598330e-01
  endloop
endfacet
facet normal 1.161178e-01 -9.870778e-01 -1.104267e-01
  outer loop
    vertex 9.483117e+00 4.764183e+00 -6.598330e-01
    vertex 7.875000e+00 4.501190e+00 0.000000e+00
    vertex 9.109818e+00 4.782848e+00 -1.219212e+00
  endloop
endfacet
facet normal 6.134766e-02 -9.843393e-01 -1.652652e-01
```


+ Additive manufacturing file format

```
<?xml version="1.0"?>
<AMF>
  <Object PrintID = "0" units = "mm">
    <Mesh>
      <Vertices>
        <Vertex VertexID="0">
          <VertexLocation x="0" y="1.332" z="3.715"/>
        </Vertex>
        <Vertex VertexID="1">
          <VertexLocation x="0" y="1.269" z="3.715"/>
        </Vertex>
        ...
      </Vertices>


      <Region FillMaterialID = "0">
        <Triangle V1 = "0" V2 = "1" V3 = "3"/>
        <Triangle V1 = "0" V2 = "1" V3 = "4"/>
        ...
      </Region>
    </Mesh>
  </Object>
</AMF>
```



+ 3MF format

<http://3mf.io/>

3MF design considerations



Complete

- Open Packaging Conventions (OPC)

Compact

- ZIP package
- References avoid duplication


Human-readable

- XML
- Well-known binary formats (e.g. PNG, JPEG)




+ MeshLab


<http://meshlab.sourceforge.net>





+ Netfabb



+ Meshmixer



FROM CAD TO CAM



+ Processing of *.stl Files



- After the CAD system has generated *.stl file, it can be passed to the SFM machine
- Machine then processes the *.stl file, slicing it into many thin layers stacked on one another. The resulting files are called slice files.
- The shapes of the slices represent cross sections
- In SFM processes thick solid sections of material are often removed and replaced with cross hatching
- Thus SFM parts are usually hollow, with cross hatching on the inside to add strength/stability

+ Support material


- Some solid freeform fabrication techniques use two materials in the course of constructing parts.
- The first material is the part material and the second is the support material (to support overhanging features during construction).
- The support material is later removed by heat or dissolved away with a solvent or water.



+ Support material




Island



Ceiling within an arch

Gussets




Ceiling


+ Patterning



Vector




Raster



Projection

+ Basic Machine Axes: 3 axis

- Cartesian Robot: 3 axis
 - X – axis (table left and right)
 - Y – axis (table in and out)
 - Z – axis (usually the extruder)



+ G-CODE


- G – Code Programming
- Originally called the “Word Address” programming format.
- Processed one line at a time sequentially.



+ Word address format

- Word address was developed as a tape programming format.
 - Another name for “word address” is “variable block” format, so named because the program lines (blocks) may vary in length according to the information contained in them.
 - Earlier tape formats required an entry for all possible machine registers. In these earlier formats, a zero was programmed as a null input if the register values were to be unaffected, but in word address, the blocks need only contain necessary information. Although developed as a tape format, word address is used as the format for manual data input on many CNC machines.
- Addresses
 - The block format for word address is as follows:
 - N ... G ... X ... Y ... Z ... I ... J ... K ... F ... H ... H ... S ... T ... M ...
 - Only the information needed on a line need be given. Each of the letters is called an address (or word)

+ Common Format of a Block



+ Word address

- Reserved Code Words Worksheet
 - N – Sequence or line number
 - G – Preparatory function
 - ...
- Dimension Words:
 - X
 - Y
 - Z



+ Word Address 1/3

- N – Sequence or line number
 - A tag that identifies the beginning of a block of code. N numbers are ignored by the controller during the program execution. It is used by operators to locate specific lines of a program when entering data or verifying the program operation.
- G – Preparatory function
 - G words specify the mode in which the milling machine is to move along its programmed axes. Preparatory functions are called prep functions or, more commonly **G codes**

+ Word Address 2/3



- Dimension Words
 - X – Distance or position in X direction
 - Y – Distance or position in Y direction
 - Z – Distance or position in Z direction
- M – Miscellaneous functions
 - M words specify CNC machine functions not related to dimensions or axial movements.

+ Word Address 3/3

- F – Feed rate (inches per minute or millimeters per minute)
 - Rate at which cutting tool moves along an axis.
- S – Spindle speed (rpm – revolutions per minute)
 - Controls spindle rotation speed.
- T – Tool number
 - Specifies tool to be selected.



+ G Word

- G words or codes tell the machine to perform certain functions. Most G words are modal which means they remain in effect until replaced by another modal G code.



+ Common G Codes

- G00 – Rapid positioning mode
 - Tool is moved along the shortest route to programmed X,Y,Z position. Usually NOT used for cutting.
- G01 – Linear Interpolation mode
 - Tool is moved along a straight-line path at programmed rate of speed.
- G02 – Circular motion clockwise (cw)
- G03 – Circular motion counter clockwise (ccw)

+ M Word

- M words tell the machine to perform certain machine related functions, such as: turn spindle on/off, coolant on/off, or stop/end program.



+ Esempio G-Code

```
;Generated with Cura_SteamEngine 13.11.2
M109 T0 S227.000000
T0
;Sliced ?filename? at: Tue 26-11-2013 17:33:05
;Basic settings: Layer height: 0.2 Walls: 0.8 Fill: 20
;Print time: #P_TIME#
;Filament used: #F_AMNT#m #F_WGHT#g
;Filament cost: #F_COST#
G21 ;metric values
G90 ;absolute positioning
M107 ;start with the fan off
G28 X0 Y0 ;move X/Y to min endstops
G28 Z0 ;move Z to min endstops
G1 Z15.0 F?max_z_speed? ;move the platform down 15mm
G92 E0 ;zero the extruded length
G1 F200 E3 ;extrude 3mm of feed stock
G92 E0 ;zero the extruded length again
G1 F9000
M117 Printing...

;Layer count: 179
;LAYER:0
M107
G0 F3600 X87.90 Y78.23 Z0.30
;TYPE:SKIRT
G1 F2400 E0.00000
G1 F1200 X88.75 Y77.39 E0.02183
G1 X89.28 Y77.04 E0.03342
G1 X90.12 Y76.69 E0.05004
G1 X90.43 Y76.63 E0.05591
G1 X91.06 Y76.37 E0.06834
```



+ Question time!



<http://goo.gl/forms/Jjm4uLd53j>

